


# CORNER RECORD

COUNTY OF Madera T. 9S R. 14E Mt. Diablo MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER  MEANDER  RANCHO  CONTROL  OTHER   
CORNER IDENTIFICATION — DATE OF VISIT 4-11- 19 77



West 1/4 corner Section 35

CORNER — LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED OBLITERATED CORNER  REBUILT

### PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 1" O.D. pipe with plastic plug marked L.S. 3733  
@ 0.6 below ground surface


### PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST  SECOND  THIRD   
STATIONS USED: NGS (USC & GS)  STATE  COUNTY  OTHER  STATION \_\_\_\_\_ STATION \_\_\_\_\_  
ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

### SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 26.05 East from "X" on North side of stand pipe
- 41.03 Northeast from nail & shiner in power pole
- 43.56 South from nail & shiner in fence post

**NOTE: THIS RECORD WAS FILED MORE THAN 90 DAYS  
AFTER THE INDICATED DATE OF VISIT.**



### SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY  
DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT  
ON LS 4156 19 77

SIGNED \_\_\_\_\_  
4156

SEAL

### COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED FEB 7 19 79  
AND EXAMINED AND FILED \_\_\_\_\_ 19 \_\_\_\_\_

BY: \_\_\_\_\_  
TITLE: MADERA COUNTY ENGINEER

DOCUMENT No. \_\_\_\_\_

STATEMENT ON BACK OF SHEET

YES  NO