

CORNER RECORD

COUNTY OF MADERA T. 6 S. R. 24 E. MD _____ MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT FEB. 1 1991



NORTH QUARTER CORNER SECTION 8

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT


PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

I FOUND THE CORNER TREE. IT IS DEAD AND DOWN. THE BEARING TREES FOR SECTIONS 5 AND 8 ARE ALSO DEAD AND DOWN.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED I SET A 3/4x30 INCH IRON PIPE AT THE CENTER OF THE STUMP HOLE CREATED BY THE FALLEN CORNER TREE. THIS IS THE SAME SITE PREVIOUSLY SELECTED BY USFS SURVEYORS. BEARING TREES ARE A 7-INCH DBH INCENSE CEDAR, 347°, 22.0 FEET AND A 6-INCH DBH PONDEROSA PINE, 201°, 43.5 FEET.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON FEB. 1 1991

SIGNED:

S.S. or R.C.E. No. S. 4126

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____

BY: _____ TITLE: _____

DOCUMENT No. _____