


CORNER RECORD

Document Number 591221 F

City of _____ County of Madera, California

Brief Legal Description Portion of Section 7, T.5S., R.23E., M.D.B. & M.



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Corner No. 4 of the Morning Star Extension per Mineral Survey 5049AB. Found and accepted a rock mound. Corner fits bearing and distance relationship to Corner Numbers 1 and 3 of the Morning Star Ext.

A description of the physical condition of the monument as found and as set or reset: Set a 5/8" diameter bar with plastic cap LS 5339 at center of rock mound. Set 20D nail and brass tag LS 5339 at side center of bearing trees.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 1/21 1995.

Signed [Signature] L.S. or R.C.E. Number 5339



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 22 Dec 95 1995 and examined

and filed 29 JAN 96 1996
 Signed [Signature] Title ACT. CO. SURVEYOR

County Surveyor's Comment _____

