


# CORNER RECORD

Document Number 599221 C

City of \_\_\_\_\_ County of Madera, California

Brief Legal Description W 1/4 Section 7, T.5S., R.23E., M.D.B. & M.



### CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey Oct. 23, 1995

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Found 32" diameter Fir with overgrown blaze on East face. Upon opening blaze legible scribing was found. Accepted tree as 1/4 corner per field notes of Mineral Survey 5049AB by Acton, 1912. Also found original bearing trees.

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 12/21 1995.

Signed [Signature] L.S. or R.C.E. Number 5339




### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 22 Dec 1995 and examined and filed 29 JAN 1996.

Signed [Signature] Title Act. Co. Surveyor

County Surveyor's Comment \_\_\_\_\_



E 1/4 Corner, Section 7

Found 32" dia fir. with overgrown blaze on East face. Opened blaze and found a portion of the original scribing

Found 28" fir with overgrown blaze. Opened blaze and found a portion of the original scribing

N01°10'E 13.12'  
(N130°W 9.24') (GLD - Anderson 1881)

S87°38'56"E  
9.47'

Found 1" dia. iron pipe with tag LS 4261  
No Reference.

S27°50'W 15.21  
(S22°W 15.84') (GLD - Anderson 1881)

Found 36" dia fir. with surface scar. Opened tree, found no evidence of the original scribing.