


CORNER RECORD

COUNTY OF MADERA T. 5 S. R. 24 E. M.D.B. & MERIDIAN CALIFORNIA
 CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT November 19 78



NORTH 1/4 CORNER SECTION 20

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 2" I.P. with concrete plug and tag "L.S. 3920" (no reference), up 8" in 3" dia. rock mound. This rock mound and two original bearing trees per gov't. notes. Accepted as 1/4 corner common to sections 17 and 20.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GSI) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- N 81° 45' W , 42.00' Original bearing tree found to be 62" dia. Fir with bark scribing 1/4S B.T. visible. Original gov't. notes show this bearing tree to be 4" dia.
- S 26° 53' E , 11.20' Original bearing tree found to be 32" dia. Fir with grown over blaze.
- N 69° 15' E , 15.37' Set chiseled "X" in rock.
- S 49° 45' E , 22.92' Set chiseled "X" in rock.
- S 01° 15' W , 11.98' Set nail and washer stamped "L.S. 3670" in rock.
- N 42° 15' W , 50.34' Set nail and washer stamped "L.S. 3670" at base of 13" dia. White Fir, on right side.

NOTE: Copied from Record of Survey for Southern California Edison Co. by Robert S. Hodson L.S. 3670

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____

SIGNED: _____

L.S. or R.C.E. No.: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET YES NO