


# CORNER RECORD

Document Number \_\_\_\_\_

City of \_\_\_\_\_

County of MADERA, California

Brief Legal Description NW COR. SEC. 20 5/24



### CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey \_\_\_\_\_

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

\_\_\_\_\_ N.W. CORNER SECTION 20, 5/24  
 \_\_\_\_\_ 2 1/2" ODIP W/ USFS ALUMINUM CAP  
 \_\_\_\_\_ L.S. 4689 CAIRN UP 0.6' "T.F."

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_

TIES (m): NB6°52'45"E 67.64' TO A 3 1/2" WHITE FIR (DBH) FO NAIL ON E/S  
 S 06°42'25"E 77.41' TO A 25" JEFFREY PINE (DBH) SET NAIL ON N/S  
 S 84°36'05"E 45.66' TO A 2" ODIP (UP 0.7") TAGGED LS 3720

**COPIED FROM RS 46/134**

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on \_\_\_\_\_ 19 \_\_\_\_.

Signed \_\_\_\_\_ L.S. or R.C.E. Number \_\_\_\_\_

### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_ 19 \_\_\_\_ and examined and filed \_\_\_\_\_ 19 \_\_\_\_.

Signed \_\_\_\_\_ Title \_\_\_\_\_

County Surveyor's Comment \_\_\_\_\_