


CORNER RECORD

Document Number 49215

City of _____ County of Modoc, California

Brief Legal Description E 1/4 Corner, Sec. 29, T.6.S., R.20 E., M.D.B.M.



CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Scaled approx. positions on USGS quad. Chained along E-W fence from County Rd. 812. Found original GLO stone and 2 original bearing trees at scaled position, 1275' ± easterly of gate in fence on Road 812.

A description of the physical condition of the monument as found and as set or reset: _____

Found stone 13 1/2" x 3" x 5" out of ground, marked 1/4 on west face (barely legible). Also found a blazed 30" digger pine to the NE per the GLO notes and a 24" digger pine, blazed, to the SW per GLO notes. Set 3/4" rebar with a plastic cap stamped L.S. 5339 East 0.15' from the top center of the stone. See sketch on back.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on May 10 1994.

Signed Richard A. Seaman (L.S.) or R.C.E. Number 5339

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 5-12 1994 and examined and filed 5-23 1994.

Signed Kell Title EDG. TECH

County Surveyor's Comment _____



18.00



NOTE: Approx. Section line does not cross Chowchilla River for first 500' ± north of 1/4 corner (at least). Did not check further north.

Rd 812
Gate

1275' ±

S80°W 17'

R 13" x 3" x 5" UP stone

Found blazed 30" digger pine, N67 1/4° E 29.04'

S33 1/4° W 19.80'

Found blazed 24" digger pine



0620300240