


OK

# CORNER RECORD

COUNTY OF Madera T. 9S R. 14E Mt. Diablo MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER  MEANDER  RANCHO  CONTROL  OTHER

CORNER IDENTIFICATION — DATE OF VISIT 4-15- 19 77



Northwest corner Section 36

CORNER — LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED OBLITERATED CORNER  REBUILT

### PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 1" O.D. pipe with plastic plug marked L.S. 3733 @ 0.5 below road surface

### PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED


Also found a 7/8" O.D. pipe 2.10 North of 1" O.D. pipe L.S. 3733

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST  SECOND  THIRD   
STATIONS USED: NGS (USC & GS)  STATE  COUNTY  OTHER  STATION \_\_\_\_\_ STATION \_\_\_\_\_  
ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

### SKETCH: (Include reference tie or witness points, remarks and topo of area)

38.80 Southeast from nail & shiner in power pole  
47.27 Northwest from nail & shiner in stop sign  
65.05 Southwest from nail & shiner in 4 x 4 post

NOTE: THIS RECORD WAS FILED MORE THAN 90 DAYS AFTER THE DATE OF VISIT.



**SURVEYOR'S CERTIFICATE**  
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT  
ON APR. 24 19 77  
SIGNED: John E. Davis  
4156

SEAL

**COUNTY SURVEYOR'S CERTIFICATE**  
THE CORNER RECORD WAS RECEIVED FEB 7 19 79  
AND EXAMINED AND FILED \_\_\_\_\_ 19\_\_\_\_\_  
BY: \_\_\_\_\_  
TITLE: \_\_\_\_\_  
DOCUMENT No. \_\_\_\_\_  
STATEMENT ON BACK OF SHEET YES  NO