City of		Document Number	
. ,	County of	<u>Madera</u>	, California
ief Legal Description North Quarter Corner Section	14 T6S, R21E, MDN	М	
CORNER TYPE			COORDINATES (Optional)
	roperty ther	E	Datum
Corner Left as found _ Found and tagged _	Established _	Reestablished	_ Rebuilt _
Identification and type of corner found: Evidence used to id	dentify or procedure	used to establish o	or reestablish the corne
Corner position established at record bearing and c (Magnetic declination 16°E)	listance from found	d original Black O	ak bearing tree.
Set F.S.M., up 10". Built rock mound 2 1/2' diameter Forest Service monument signs attached 4' +/- SE o	f the corner.		
Set F.S.M., up 10". Built rock mound 2 1/2' diameter Forest Service monument signs attached 4' +/- SE of F.S.M Aluminum monument, 2 1/2" O.D., 30" long with LS 6806, the date, and the Forest Service logo. SURVEYOR'S STATEMENT	f the corner.	aluminum cap star	nped for the corner,
Forest Service monument signs attached 4' +/- SE or F.S.M Aluminum monument, 2 1/2" O.D., 30" long with LS 6806, the date, and the Forest Service logo.	f the corner. with a 3 1/4" O.D. a	aluminum cap star	
Forest Service monument signs attached 4' +/- SE of F.S.M Aluminum monument, 2 1/2" O.D., 30" long with LS 6806, the date, and the Forest Service logo. SURVEYOR'S STATEMENT	f the corner. with a 3 1/4" O.D. a	aluminum cap star	nped for the corner,
Forest Service monument signs attached 4' +/- SE of F.S.M Aluminum monument, 2 1/2" O.D., 30" long with LS 6806, the date, and the Forest Service logo. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direct with the Land Surveyors' Act onAugust 111	f the corner. with a 3 1/4" O.D. a tion in conformance	aluminum cap star	DIAND SURVEY, AN B. JORONA, COOK
Forest Service monument signs attached 4' +/- SE of F.S.M Aluminum monument, 2 1/2" O.D., 30" long with LS 6806, the date, and the Forest Service logo. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direct with the Land Surveyors' Act onAugust 111	f the corner. with a 3 1/4" O.D. a tion in conformance 9 98 mber 6806	aluminum cap star	DIAND SURVINOS AND SURVINOS AND B. JORDAN D. 9-30-2000
Forest Service monument signs attached 4' +/- SE of F.S.M Aluminum monument, 2 1/2" O.D., 30" long with LS 6806, the date, and the Forest Service logo. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direct with the Land Surveyors' Act onAugust 11	f the corner. with a 3 1/4" O.D. a tion in conformance 9 98 . mber 6806	aluminum cap star	DIAND SURVEY, AN B. JORONA, D. 9-30-2000
Forest Service monument signs attached 4' +/- SE of F.S.M Aluminum monument, 2 1/2" O.D., 30" long with LS 6806, the date, and the Forest Service logo. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direct with the Land Surveyors' Act onAugust 111 Signed Justin B Jondan L.S. or R.C.E. Nu	tion in conformance 9 98 mber 6806 T	aluminum cap star	DIAND SURVEY, AN B. JORONA, COOK

Corner Ties:

Original Bearing Tree:

1. A Black Oak, 28" dia., with open blaze and ax marks visible, bears \$29 3/4°W, 54.78'.

New Bearing Trees:

- 1. An Incense Cedar, 10" dia., bears N70°W, 13.90'.
- 2. A Ponderosa Pine, 11" dia., bears S32°E, 38.55'.

Cap Inscription:

T6S R21E S 11 S 14 LS 6808 1998

Found a depression N7°E, 30' +/-.

The corner lies approximately 440' west of a ravine running south-southwesterly and approximately 820' east of a ravine running southwesterly.

Bearings are to the center of trees at the base. Distances are horizontal to a nail driven into the side center of the root crown.

Posted Forest Service monument and bearing tree signs.

0621540500