


# CORNER RECORD

Document Number \_\_\_\_\_

City of \_\_\_\_\_

County of Madera, California

Brie. Legal Description \_\_\_\_\_



### CORNER TYPE

S 30 6/21

### COORDINATES

(OPTIONAL)

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey June 7, 1996

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone Datum  
 Elevation \_\_\_\_\_

CORNER -- Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:  
*Found East 1/4 Section 30 and Southeast corner Section 30.  
 Set 1/16 corner at midpoint*

A description of the physical condition of the monument as found and as set or reset:  
*Set 3/4" iron pipe witness corner, flush, tagged PLS 7061, 40.00 feet east of true position.  
 True position lies in the center of Miami Creek.*

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on July 16, 1996.

Signed Travis Davis PLS 7061




### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_ 1996 and examined


and filed 7 FEB 1996

Signed Mark Rickford Miller Title ACT. CO. SURVEYOR



Co. Surveyor's Comment: CORNER RECORD WAS FOUND IN PAPERWORK + RECORDED LATE.

East 1/4 Section 30. G/21  
found stone with nail + L5  
4298 tag on top. "TF"



1321.62'

(N 00°01' W 2640') government notes

2643.25'

N 89°11'00" W  
40.00'

Set 3/4" iron pipe  
Witness Corner

N 00°49'00" E  
27 PG. 40, M.C.R.

1321.63'

(N 01°01'13" E

SE corner of Section 30 G/21  
found stone up 12'. 4 grooves on  
west side, one groove on north  
side, nail + L5 4261 tag on top  
of stone, ties per Book 38,  
Page 32, M.C.R.

0621200220