


**CORNER RECORD**

Document Number \_\_\_\_\_

Town of **Oakhurst**

County of **Madera, California**

Brief Legal Description: **Northeast corner of Lot 5 Yosemite Forks Estates #4 Section 36 6/21**



**CORNER TYPE**

Government Corner   
Meander   
Rancho   
Date of Survey: **September 9, 2003**

Control   
Property   
Other   
Elevation \_\_\_\_\_

**COORDINATES (Optional)**

N.  
E.  
Zone

CORNER -- Let as found  Found and tagged  Established  Re-established  Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or re-establish the corner:

**Set 5/8" rebar and cap LS. 4298 flush in Ac driveway at record position for Lot 5 Yosemite Forks Estates #4 Est. from found original corners on East South of Lot #1 and original corners on West South of Lot #5 and South West of Lot #5 and South West corner Lot 47.**


A description of the physical condition of the monument as found and as set or reset:

**Also found 3/4" iron pipe, flush in driveway S.72°38'57"W. 8.07 feet not accepted source unknown**

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors Act on **September 10, 2003**

Signed \_\_\_\_\_ **Stephen L. Jones** LS 4298



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received SEPTEMBER 15 2003 and examined and filed SEPTEMBER 26 2003

Signed David M. McGlasson Title ACTING CO. SURVEYOR



County Surveyor's Comment: No drawing or sketch was included with this corner record.