


**CORNER RECORD**

Document Number \_\_\_\_\_

Town of **Oakhurst**

County of **Madera, California**

Brief Legal Description: **Southeast corner of Lot 5 Yosemite Forks Estates #4 Section 36 6/21**



**CORNER TYPE**

Government Corner   
 Meander   
 Rancho   
 Date of Survey: **September 9, 2003**

Control   
 Property   
 Other   
 Elevation \_\_\_\_\_

**COORDINATES (Optional)**

N.  
 E.  
 Zone

CORNER -- Let as found  Found and tagged  Established  Re-established  Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or re-establish the corner:

**Set 5/8" rebar and cap LS. 4298 up 4" on West slope of Buckeye Road, at record position for Lot #5 Yosemite Forks Estates #4 Est. from found original corners on East South of Lot #1 and West South of Lot #5 and South West corner Lot #47**


A description of the physical condition of the monument as found and as set or reset:

**Also found 1" iron pipe, up 3" under Oak tree S.88°04'19"W. 4.56 feet not accepted, source unknown**

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with  
 the Land Surveyors' Act on **September 10, 2003**

Signed \_\_\_\_\_ **LS 4298**  
**Stephen L. Jones**



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received SEPTEMBER 15 2003 and examined  
 and filed SEPTEMBER 26 2003

Signed David McGlasson Title ACTING Co. SURVEYOR

**12.31.03**

County Surveyor's Comment: No sketch or drawing was provided with this corner record.

