

**CORNER RECORD**

COUNTY OF MADERA COUNTY T. 6 S. R. 22 E. M.D.B. # MERIDIAN CALIFORNIA  
 CORNER TYPE: GOV'T. CORNER  MEANDER  RANCHO  CONTROL  OTHER   
 CORNER IDENTIFICATION - DATE OF VISIT JULY 30, 1976



NORTH 1/4 CORNER SECTION 7

CORNER - LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED OBLITERATED CORNER  REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

RESET FROM ORIGINAL NE BEARING TREE

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

SET 2" X 30" IRON PIPE W/ 2" BRASS CAP MON. - L.S. 2737 UP 24"  
 IN STONE MOUND

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST  SECOND  THIRD   
 STATIONS USED: NGS (USC & GS)  STATE  COUNTY  OTHER  STATION \_\_\_\_\_ STATION \_\_\_\_\_  
 ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

SKETCH: (Include reference tie or witness points, remarks and topo of area)

ON W/S FOREST SERVICE ROAD - AGAINST CUT BANK.  
 7' ± W. OF CENTERLINE OF ROAD.  
 POSITION FOR 30" CEDAR N. 38° 45' E. 15.85' (ORIG. B.T.) (SCRIBING VISIBLE).  
 THIS TREE HAD BEEN BULLDOZED TO E/S OF ROAD (ABOUT 30' E)  
 POSITION DETERMINED FROM PROTUDING ROOTS IN CUT BANK  
 W/S ROAD - (WHICH MATCH CUT OFF ROOTS ON TREE TRUNK)  
 13" CEDAR N. 47° 10' E. 57.70' } I BLAZED & SCRIBED  
 13" CEDAR S. 3° 10' E. 26.90' }  
 315' ± E. OF CREST OF RIDGE  
 305' ± E. OF 12" CEDAR (W/K-TAG)  
 ORIGINAL SE B.T. (BLACK OAK) ALSO BULLDOZED TO E/S ROAD.  
 BEARINGS BASED ON MAGNETIC - VARIATION N. 17° E.  
 J.N. 76-101  
 F.B. 541 p. 47

**SURVEYOR'S CERTIFICATE**

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON AUGUST 21, 1976.

SIGNED: William D. Gentry  
 L.S. or R.C.E. No.: 2737

SEAL

**COUNTY SURVEYOR'S CERTIFICATE**

THE CORNER RECORD WAS RECEIVED 8.10. 1976 AND EXAMINED AND FILED AUG 11 1976.  
 BY: A. Grate  
 TITLE: County Engineer  
 DOCUMENT No. 76-20.4

STATEMENT ON BACK OF SHEET  
 YES  NO