

CORNER RECORD

COUNTY OF MADERA T. 6 S. R. 24 E. MD MERIDIAN CALIFORNIA
 CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT FEB. 1 1991



NORTH QUARTER CORNER SECTION 5

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

I FOUND THE ORIGINAL STONE MOUND. IN ADDITION, THE BEARING TREE FOR SECTION 32 IS INTACT. THE BEARING TREE FOR SECTION 5, A BLACK OAK, HAS DIED AND THE SNAG IS DOWN.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

I SET A 3/4x30 INCH IRON PIPE AT THE CENTER OF THE ORIGINAL MONUMENT. THE DISTANCE WAS CONFIRMED FROM THE SECTION 32 BEARING TREE. THE STONE MOUND WAS REBUILT. BEARING TREES ARE A 9-INCH DBH PONDEROSA PINE, 7⁰, 20.3 FEET AND A 10-INCH DBH INCENSE CEDAR, 175⁰, 33.1 FEET.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON FEB. 1 1991
 SIGNED: *[Signature]*

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19_____
 AND EXAMINED AND FILED _____ 19_____
 BY: _____
 TITLE: _____
 DOCUMENT No. _____