## CORNER RECORD

COUNTY OF MADERA 7 6 S. 24	1 E. MD ASSIDIAN CAUFORNIA
	CONTROL [7] OTHER [7]
*	
Northwest Corner Section	
CORNER LEFT AS FOUND FOUND AND TAGGED REESTABL	ISHED OBLITERATED CORNER [] REBUILT []
PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED T	TO IDENTIFY OR REESTABLISH
I FOUND THE ORIGINAL STONE MOUND; THE ST ADDITION, THE BEARING TREE FOR SECTION 8 SECTIONS 5 AND 9 ARE DEAD AND DOWN; THEIR TREE FOR SECTION 4 IS DEAD; IT WAS A FELL	IS INTACT. THE BEARING TREES FOR STUMPS ROTTED AWAY. THE BEARING
I PULLED THE STONE POST AND SET A 3/4x30 inch iron pipe at the center of the original monument. The distance was confirmed from the Section 8 Bearing Tree. The stone mound was rebuilt using the original stone post as a cap stone. I marked a 5-inch obb ponderosa pine at 39°, 20.8 feet; a 18-inch obb incense cedar at 96.5°, 31.8 feet; and a 4-inch obb sugar pine at 218.5°, 13.2 feet for New Bearing Trees. The original Bearing Tree for Section 8, a 34-inch ponderosa pine, is 216°, 10.0 feet.	
CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND	THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY	OTHER STATION STATION
	EASTINGS (R)
SKETCH: (Include reference tie or witness points, remarks and topo of ar	
CHARLES VICTOR S	
SIKBRA	
NO. 4126	
THE OF CALIFORNIA	
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY	COUNTY SURVEYOR'S CERTIFICATE THE CORNER RECORD WAS RECEIVED
DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT	AND EXAMINED AND FILED 10
	true
SIGNED: ALL	나는 그는 사람들은 살아 살아 들어 되었다. 그 사람들은 얼마를 하는 것이 없는 것이 없는 것이 없는 것이다.