


# CORNER RECORD

Document Number \_\_\_\_\_

City of \_\_\_\_\_

County of MADERA, California

Brief Legal Description \_\_\_\_\_



### CORNER TYPE

- Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey SEPT. 17, 1995

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

A description of the physical condition of the monument as found and as set or reset:

NORTHEAST CORNER, SECTION 23 1/4  
PO. (1) ORIG. BT & STUMP HOLE AT FALLEN OAK,  
SET 5/8" REBAR L.S. 5509 IN FOUND ROCK 11/2  
FROM WHICH BEARS:  
 STUMP HOLE N 29° W 44.8'  
 30" W OAK S 59° W 12.95'  
 16" W OAK STUMP S 1° E 13.43'  
 22" W OAK W HEALED BLAZE S 78° E 13.43'  
 N+T IN 4" DIA. ROCK N 60° E 7.68'  
 N+T IN 6" DIA. ROCK N 75° W 9.23'  
 N+T IN 2x6x2" HIGH ROCK S 28° W 32.54'

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on \_\_\_\_\_ 19 \_\_\_\_ .

Signed \_\_\_\_\_ L.S. or R.C.E. Number \_\_\_\_\_

### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_ 19 \_\_\_\_ and examined and filed \_\_\_\_\_ 19 \_\_\_\_ .

Signed \_\_\_\_\_ Title \_\_\_\_\_

County Surveyor's Comment COPIED FROM JONES & SNYDER  
RECORD OF SURVEY, RECORDED IN BOOK 44 OF MAPS  
AT PAGE 145