


CORNER RECORD

COUNTY OF MADERA T. 7 R. 19 MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT MAY 1989



W 1/4 SECTION 35 7/19

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

(17) W 1/4 CORNER SECTION 35 7/19

RE-ESTABLISHED CORNER POSITION AT RECORD BEARING AND DISTANCE FROM ORIGINAL BEARING TREE.

SET REBAR AND CAP, UP 6", NO ROCK MOUND.

ORIGINAL BEARING TREE

1. A 35.5" DIA. WHITE OAK WITH HEALED BLAZES BEARS S.59°00'W. 51.5' (S.59°W. 51.5')

NEW TIES

2. A NAIL AND TAG, LS 5509 IN A 7' X 4' X 2' HIGH ROCK BEARS N.42°E. 24.88'

3. A 19.1" DIA. WHITE OAK BEARS S.72°E. 41.72'

FOUND A 1" IRON PIPE, UP 16" WITH AN OVAL CAP STAMPED "R & I 1963" S.59°42'58"W. 55.57' FROM THE CORNER - NOT ACCEPTED

FENCE LINES RUN N'LY AND E'LY FROM THE ORIGINAL BEARING TREE

SKETCH: (incl)

COPIED FROM R.S. BY SEIB-LS. 5509 36/45-46

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____

SIGNED: _____

L.S. or R.C.E. No. _____

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET