


CORNER RECORD

COUNTY OF Madera T. 7 R. 23 M.D.B. & MERIDIAN CALIFORNIA
CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



North 1/4 corner Section 23 7/23

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT
PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found Original 4"X4" Post next to Rock Mound West side of creek

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set Mon. 2" Aluminum Pipe 25" Long with 3/4" Aluminum Cap
Stamped l.s. 4298 Rebuilt Rk. Md.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

TIES:

- West 27.66' 14" Red Fir
- N 6° E 69.33' Original 5' Fir
- S 53° E 65' New B.T. 6" W. Fir
- S 26% W 60' New B.T. 8" W. Fir

All new bearing trees blazed & scribed

Copied from R/s by Jones L.S. 4298

SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____
SIGNED: _____
L.S. or R.C.E. No.: _____
SEAL

COUNTY SURVEYOR'S CERTIFICATE
THE CORNER RECORD WAS RECEIVED _____ 19____
AND EXAMINED AND FILED _____ 19____
BY: _____
TITLE: _____
DOCUMENT No. _____
STATEMENT ON BACK OF SHEET YES NO