


CORNER RECORD

COUNTY OF MADERA T. 8 R. 19 MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT MAY 19 89



5/4 SECTION 2 8/19

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 METHODS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

(Fold)

39 S 1/4 CORNER CORNER SECTION 2 8/19

SKETCH: (Inc

FOUND ORIGINAL CORNER TREE, AN 11.8" DIA. WHITE OAK AT FENCE CORNER, FROM WHICH FENCES RUN W'LY AND S'LY.

FOUND A 1" IRON PIPE, UP 12", TAGGED L.S. 2737 N.3°22' 45" W. 1.07' FROM THE CORNER — ACCEPTED AS WITNESS CORNER.

ORIGINAL BEARING TREES:

- A. AN 11.3" DIA. WHITE OAK WITH A HEALED BLAZE BEARS N.15 1/2°E. 33.3' (N. 11°E. 32.3')
- Z. A 14.1" DIA. WHITE OAK WITH A HEALED BLAZE BEARS S. 11°W. 8.0' (S.8°W. 7.3')

M. 89-40

COPIED FROM R.S. BY SEIB-LS. 5509 36/45-46

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____

SIGNED: _____

L.S. or R.C.E. No. _____

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET