


**CORNER RECORD**

COUNTY OF MADEIRA T. 8 R. 19 MDB&M MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER  MEANDER  RANCHO  CONTROL  OTHER

CORNER IDENTIFICATION — DATE OF VISIT 7- 19 91



N 1/4 SEC. 19 8/19

CORNER — LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED OBLITERATED CORNER  REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND, EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

NORTH 1/4 COR. SEC.  
 19 8/19 PD. 0219 BT.  
 SET CORNER AT RECORDED  
 BEARING & DISTANCE  
 1) W. OAK 27" DIA. WITH OLD  
 HIGH & LOW BLADES  
 S. 65° W. 37.62 ORK. BT.  
 2) PK N.T. IN RK.  
 N. 53° W. 61.88  
 3) PK N.T. IN RK. 5278.56  
 N. 71° E. 79.64 IN  
 4) PK N.T. IN  
 RK. S. 54° E. 68.58  
 5) PD. 1/2" IR. "AN MILLER"  
 N. 92° 50' 40" W. 11.94  
 NOT ACCEPTED, SET  
 FROM BT IN ERROR  
 IN 1945.  
 N. 0° 40' 34" E.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST  SECO  
 STATIONS USED: NGS (USC & GS)  STATE  COUNTY   
 ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (N) \_\_\_\_\_

STATION \_\_\_\_\_  
 INGS (G) \_\_\_\_\_

(Fold)

SKETCH: (Include reference tie or witness points, remarks and topo of area)

*Copied from PM 3273 4/50-51*

**SURVEYOR'S CERTIFICATE**

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY  
 DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT  
 ON \_\_\_\_\_ 19\_\_\_\_

SIGNED: \_\_\_\_\_  
 L.S. or R.C.E. No. \_\_\_\_\_

SEAL

**COUNTY SURVEYOR'S CERTIFICATE**

THE CORNER RECORD WAS RECEIVED \_\_\_\_\_ 19\_\_\_\_  
 AND EXAMINED AND FILED \_\_\_\_\_ 19\_\_\_\_

BY: \_\_\_\_\_  
 TITLE: \_\_\_\_\_

DOCUMENT No. \_\_\_\_\_

STATEMENT ON BACK OF SHEET  
 YES  NO