


CORNER RECORD

Document Number _____

City of _____

County of MADERA, California

Brief Legal Description E 1/4 COR. SEC 16 T8S, R19E



CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

EAST 1/4 CORNER
SECTION 16 T8S
1/4" IRON PIPE
R.C.E. 1978
TIES:
12" W. OAK N. 15° 26' 56" W. 25.74
22" W. OAK N. 6° 39' 58" E. 50.98

Condition of the monument as found and as set or reset: _____

COPIED FROM P.M. 3779

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on _____ 19____.

Signed _____ LS. or R.C.E. Number _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 19____ and examined and filed _____ 19____.

Signed _____ Title _____

County Surveyor's Comment _____

