


CORNER RECORD

Document Number _____

City of _____

County of Madera, California

Brief Legal Description _____



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES

(OPTIONAL)

N. _____
 E. _____
 Zone _____ Datum _____
 Elevation _____

CORNER -- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

Found Center of Section 9, Township 8 South, Range 21 East, Mount Diablo Base and Meridian,
 per Record of Survey filed in Book 14, Page 1, Madera County Records by C.J. McKee in September, 1966.

A description of the physical condition of the monument as found and as set or reset:

Found 2" iron pipe, in rock mound, up 3", tagged R.C.E. 5982.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyors' Act on March 13, 1996

Signed Travis Davis PLS 7061



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 1 APRIL 1996 and examined
 and filed 9 APRIL 1996.

Signed MARIE MILLER Title ACTING COUNTY SURVEYOR



County Surveyor's Comment: _____



SCALE 1" = 10'

SET NAIL AND TIN IN WEST SIDE OF 14" LIVE OAK.

17.87

CENTER SEC. 9, T8 S, R21 E M.D.B. & M.

1.0'

BARB WIRE FENCE

0.5'

19.07

SET NAIL AND TIN IN NORTHWEST SIDE OF 14" LIVE OAK.

0821240600

