

CORNER RECORD

Agency Index _____


Document Number _____

City of _____ County of Madera, California

Brief Legal Description Southeast Corner Section 10, T.8S., R.21E., M.D.B.&M.

CORNER TYPE

COORDINATES (Optional)



- Government Corner Control
 Meander Property
 Rancho Other

N. _____ E. _____

Elevation _____

Units Metric U.S. Survey Foot

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

Complies with Public Resources Code §§8801-8819

Complies with Public Resources Code §§8890-8902

Date of Survey March 8, 2022

PLS Act Ref.: 8765(d) 8771 8773 Other:

Corner/
Monument: Left as found Established Rebuilt Pre-Construction

Found and tagged Reestablished Referenced Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):

Found 2' diameter stone mound, 6" high on southwest slope. Found original 36" (20") white oak , North 60° East, 183'+-. Found original 30" oak stump (30" white oak) south 226'+-. Set 3/4" iron pipe up 6" in stone mound, PLS7061 tag. 15' northeast of the centerline of the Narbo Ditch
 Set nail & tin in a 15" white oak, South 20.0° East, 62.80'.
 Set nail & tin in a 15" live oak, North 10.0° East, 27.50'.
 Set nail & tin in a 24" live oak, North 22.5° West, 22.12'.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on March 24, 2022

Signed Travis Davis P.L.S. or R.C.E. No. 7061

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUG 15th, 2022

and examined and filed AUG. 17th, 2022

Signed [Signature] P.L.S. or R.C.E. No. 4037

Title CO-ACTING CO. SURVEYOR

County Surveyor's Comment

NO COMMENTS!

