


CORNER RECORD

Document Number 6995

City of _____ County of Madera, California

Brn Legal Description Portion Section 17, T.8S., R.21E., M.D.B.& M.,
Parcel No. 3 of Parcel Map No. 1665, Book 26, Page 107, Madera Co. Records.



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey May 7, 1996

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Re-established southeast right-of-way corner at record position per Parcel Map No. 1655,
Madera County Records.

A description of the physical condition of the monument as found and as set or reset: _____

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyors' Act on May 9 19 96.

Signed [Signature] L.S. or R.C.E. Number L.S. 5339


COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 17 MAY 19 96 and examined

and filed 20 MAY 19 96.

Signed [Signature] Title Assoc. Co. Surveyor

County Surveyor's Comment _____



960425

(1) Parcel Map No. 1665, Book 26 Page 107, Madera Co. Records.

(M) Measured Data

- Found 1" diameter Iron Pipe per (1)

