


# CORNER RECORD

COUNTY OF Madera T. 8 S. R. 22 & 29E. M.D. \_\_\_\_\_ MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER  MEANDER  RANCHO  CONTROL  OTHER

CORNER IDENTIFICATION -- DATE OF VISIT March 17 1989



Quarter Corner for Sections 12 and 7

CORNER -- LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED OBLITERATED CORNER  REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND, EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

diameter iron pipe with brass cap, tagged LS1969, was found for the corner. This monument has been established and used for many years; no original evidence was found. A  $\frac{1}{2}$  inch

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

The monument was left as found. A north/south barb-wire fence is 3 feet west of monument. Bearing trees are: 12" dbh liveoak, in the fence line, S82°W, 3.0 feet; 6" dbh liveoak, with USFS K-tag, N66°E, 8.0 feet; 8" dbh black oak, S74°E, 27.8 feet.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST  SECOND  THIRD

STATIONS USED: NGS (USC & GS)  STATE  COUNTY  OTHER  STATION \_\_\_\_\_ STATION \_\_\_\_\_

ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

SKETCH: (Include reference tie or witness points, remarks and topo of area)



**SURVEYOR'S CERTIFICATE**

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON March 17 1989.

SIGNED: [Signature]  
L.S. or R.C.E. No. 4126

**COUNTY SURVEYOR'S CERTIFICATE**

THE CORNER RECORD WAS RECEIVED AND EXAMINED AND FILED 4-3 1989 BY: [Signature]  
TITLE: County Engineer

DOCUMENT No. \_\_\_\_\_

STATEMENT ON BACK OF SHEET YES  NO