


CORNER RECORD

COUNTY OF Madera T. 8 S. R. 22 E. M.D.B.& MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER  MEANDER  RANCHO  CONTROL  OTHER

CORNER IDENTIFICATION — DATE OF VISIT 1-27- 19 75



CORNER — LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED OBLITERATED CORNER  REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 1 3/4" Iron Pipe and accepted as the N 1/4 corner Section 24.  
Tagged L.S. 3920

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST  SECOND  THIRD   
STATIONS USED: NGS (USC & GS)  STATE  COUNTY  OTHER  STATION \_\_\_\_\_ STATION \_\_\_\_\_  
ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 0.5' South of Fence West
- 1.0' South of Fence East
- 1.0' Southeast of Nail and Shiner in Fence Post
- 1.5' Southwest of Nail and Shiner in Fence Post


Corner is 10" above.

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY MS W. HURLEY OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON 1-28-

SIGNED: [Signature]

L.S. or R.E.S. No.: 2924



SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED Aug 25 19 75 AND EXAMINED AND FILED Aug 25 19 75

BY: [Signature]  
TITLE: Co. Insp. Asst

DOCUMENT No. 75-30-01

STATEMENT ON BACK OF SHEET

YES  NO

county Surveyor's Note:

The monument was described earlier in P.M. 523 by Ron Greenwood that it was tagged R.C.E. 12,406. The only discrepancy is the number of tag numbers.

Green

0822 648 400