


CORNER RECORD

COUNTY OF MADERA T. 9S. R. 17E. M.D.B. & MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER  MEANDER  RANCHO  CONTROL  OTHER

CORNER IDENTIFICATION - DATE OF VISIT NOVEMBER 10 19 76



WEST 1/4 SECTION 13  
CORNER

CORNER - LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED OBLITERATED CORNER  REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND 3/4 " IRON PIPE - 12" DOWN

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

I TAGGED L.S. 2737

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST  SECOND  THIRD   
STATIONS USED: NGS (USC & GS)  STATE  COUNTY  OTHER  STATION \_\_\_\_\_ STATION \_\_\_\_\_  
ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

SKETCH: (Include reference tie or witness points, remarks and topo of area)

0.4' ± NW OF BROKEN STEEL FENCE POST - FLUSH.  
0.3' SOUTH OF FENCE W.  
0.3' NORTH ✓ ✓ E.  
4.8' EAST ✓ ✓ S.  
9.1' SE ✓ 3" STEEL POST.  
1.4' W. ✓ POWER LINE S.  
2.8' W. ✓ ✓ N. (OMIT 1ST POLE).  
19.0' W. ✓ C/L OF ROAD N. & S.  
43.3' W. ✓ FENCE N., E/S ROAD.  
50.20' W. ✓ CORNER FENCE POST.  
J.N. 76-145 F.B. 545/50

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON NOVEMBER 22 19 76.

SIGNED: William D. Gentry

L.S. & C.E. No.: 2737

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED DECEMBER 6 19 76 AND EXAMINED AND FILED DEC 13 19 76.

BY: A. Lynte

TITLE: Co. Engineer

DOCUMENT No. 76-37-04

STATEMENT ON BACK OF SHEET

YES

NO