


CORNER RECORD

Document Number _____

City of _____

County of MADERA, California

Brief Legal Description N 1/4 CORNER SEC. 25, T. 9E., R. 17S., M.D.B&M.



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey APRIL 24, 2008

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND 5/8" BAR LYING ON ITS SIDE, RESET 2" IRON PIPE WITH BRASS CAP PER CORNER RECORD TIES ON FILE WITH MADERA COUNTY, DATED 10-23-1985. IT WAS FOUND THAT THE DISTANCES TO THE N.E. TIE AND THE S.W. TIE WERE REVERSED, THIS WAS CONFIRMED WITH 42 R.S. 23 WITH DISTANCES TO THE N.W. & N.E. SECTION CORNERS.

A description of the physical condition of the monument as found and as set or reset: SET 2" IRON PIPE WITH BRASS CAP DOWN 4." SEC TIES ON REVERSE SIDE.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on July 1, 2008

Signed [Signature] P.L.S. or R.C.E. No. 7621




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 8/21/08

and examined and filed 8/24/08

Signed David M. McGlasson P.L.S. or R.C.E. No. 6968

Title ACTING CO. SURVEYOR



County Surveyor's Comment _____

NORTH 1/4 COR. SEC. 25, 9/17
SET 2" IRON PIPE WITH
BRASS CAP, DOWN 4"

N.E. CORNER SEC. 25, 9/17
FOUND 1/2" BAR No TAG
(42 M. 23) PER TIES ON FILE

N.W. CORNER SEC. 25, 9/17
FOUND 3/4" IRON PIPE WITH
L.S. 7442 TAG (42 M. 23)
PER TIES ON FILE

FOUND NAIL & SHAWER
IN POWER POLE

2631.32' (2631.28' 42 M 23)

115' 15"

AVENUE 26

2630.64'
(2630.69' 42 M 23)

47' 15"

400'

1' 6"

FOUND NAIL & SHAWER
IN POWER POLE

SET 3/4" IRON PIPE
WITH L.S. 7621 TAG
ON 1/4 SECTION LINE.

ROAD 26

BARBED WIRE
FENCE

NORTH