


CORNER RECORD

COUNTY OF MADERA T. 9S. R. 18E. M.D.B. & MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT NOVEMBER 15 1976



NORTHWEST CORNER SECTION 10

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND 2"x2" RWD - UP 2"

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

REPLACED STAKE WITH 2"x30" IRON PIPE - L.S. 2737 - UP 9"
IN STONE & EARTH MOUND. - RESET RWD STAKE ON
E/S OF PIPE.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

53.70' SE OF O NE COR. N. BRACE POST R/W FENCE E/S ROAD.
91.10' NE ✓ O TOP FENCE POST.
44.90' E. ✓ R/W FENCE E/S BUCHANAN ROAD.
J.N. 76-145 F.B. 545 p. 50

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON NOVEMBER 22 1976.

SIGNED: William D. Gentry

L.S. or R.C.E. No.: 2737

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED DECEMBER 6 1976 AND EXAMINED AND FILED Dec 13 1976.

BY: A. Gato

TITLE: County Engineer

DOCUMENT No. 76-37-69

STATEMENT ON BACK OF SHEET

YES

NO