


CORNER RECORD

COUNTY OF Madera T. 9 S. R. 19 E. M.D. _____ MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT July 20 1989



Quarter Corner - Sections 10 and 11

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH


The original corner has been lost.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

I reestablished the corner by single proportion measurement. I set a 3/4x30 inch iron pipe with a plastic plug and brass tag (LS4126) in the earth and up 6 inches. From which bears a 22" dbh blue oak, S20°E, 78.4 feet.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON July 20 1989

SIGNED _____

L.S. or R.C.E. No. _____

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED 8-15 1989 AND EXAMINED AND FILED 8-16 1989

BY: D. S. Stinson
TITLE: County Engineer

DOCUMENT No. _____