

CORNER RECORD

COUNTY OF MADERA T. B.S. R. 19E. M.D.B. & MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT MARCH 9, 1989



WEST 1/4 CORNER SECTION 2 8/19

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

CORNER RE-ESTABLISHED FROM ORIGINAL SW BEARING TREE - FIRST FOUND 3-18-1980

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

SET 1" x 30" IRON PIPE W. PLASTIC PLUG - L.S. 2737 UP 8" IN STONE MOUND,

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

ON NW SLOPE
0.8' N. of New Fence W.
2.6' S. of Old Fence E. — Begins 19.4'E.
19.4' W. of Old Fence S.

FROM WHICH CORNER BEARS:

15" Oak - Blazed S. 67° 00' W. 27.72 (10" Oak S. 67° W. 27.72) Orig. B.T.
25" Oak - OPEN BLAZE NW/S S. 38° 10' E. 55.57' (30" Oak S. 15° E. 56.76')
Possible Orig. B.T. — But Not Used For Control.
4" Oak S. 1° 47' E. 31.18' — Made Small Blaze on N/S.

J.N. 80-044 & 89-025

F.B. 552/72, 84

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON MARCH 10, 1989

SIGNED: William O. Gentry

L.S. of C.E. No.: 2737
EXPIRES: 6-30-1992

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED AND EXAMINED AND FILED 4 1989
BY: Donald J. ...
TITLE: County Engineer

DOCUMENT No. _____
STATEMENT ON BACK OF SHEET

