

CORNER RECORD

COUNTY OF MADERA T. 8 S. R. 23 E. M.D.B. & MERIDIAN CALIFORNIA
CORNER TYPE: GOVT. CORNER [X] MEANDER [] RANCHO [] CONTROL [] OTHER []
CORNER IDENTIFICATION - DATE OF VISIT AUGUST 1978



SOUTHEAST CORNER SECTION 33

CORNER - LEFT AS FOUND [X] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [] REBUILT []

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

1 1/2" iron pipe in rock mound tagged L.S. 2773

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD []
STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

TIES

S 3° 30' W 87.7 feet to set nail in rock bluff
Corner is ~ 40 feet South of Mammoth road

Copied from Record of Survey for Herbert Glover by Douglas A. Breadahl
L.S. 4509

SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19_____
SIGNED: _____
L.S. or R.C.E. No.: _____
SEAL

COUNTY SURVEYOR'S CERTIFICATE
THE CORNER RECORD WAS RECEIVED _____ 19_____
AND EXAMINED AND FILED _____ 19_____
BY: _____
TITLE: _____
DOCUMENT No. _____
STATEMENT ON BACK OF SHEET YES [] NO []