


# CORNER RECORD

COUNTY OF Madera T. 9 S R. 15 E Mt. Diablo MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER  MEANDER  RANCHO  CONTROL  OTHER

CORNER IDENTIFICATION — DATE OF VISIT March 19, 19 76



Northwest corner Section 27

CORNER — LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED OBLITERATED CORNER  REBUILT

### PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 1½" x 3" redwood with 1½" iron pipe on Eastside at 1' below road surface.


### PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST  SECOND  THIRD   
STATIONS USED: NGS (USC & GS)  STATE  COUNTY  OTHER  STATION \_\_\_\_\_ STATION \_\_\_\_\_  
ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

### SKETCH: (include reference tie or witness points, remarks and topo of area)

33.55 Southeast from nail & shiner in Telephone pole.  
38.64 Northwest from nail & shiner in power pole.

NOTE: THIS RECORD WAS FILED MORE THAN 90 DAYS AFTER THE INDICATED DATE OF VISIT.



### SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY SUPERVISION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON January 29, 19 78

SIGNED: Johnny E. Barris

No.: 4156

SEAL

### COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED FEB 7 19 79 AND EXAMINED AND FILED \_\_\_\_\_ 19 \_\_\_\_\_

BY: \_\_\_\_\_  
TITLE: MADERA COUNTY ENGINEER

DOCUMENT No. \_\_\_\_\_

STATEMENT ON BACK OF SHEET

YES  NO