


# CORNER RECORD

Document Number \_\_\_\_\_

City of \_\_\_\_\_

County of \_\_\_\_\_, California

Brief Legal Description 3 1/4 COR SEC 17 6/22



### CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey \_\_\_\_\_

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ NAD27  NAD83   
 NAD83 Epoch \_\_\_\_\_  
 Elev. \_\_\_\_\_  
 Vert. Datum: NGVD29  NAVD88   
 Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

② SOUTH 1/4 CORNER SEC. 17 6/22  
 PD. ROCK MD. AND 2 B.T.  
 RESET W/ U.S. F.S. MON. IN ROCK MD. L.S. 4298  
 FROM WHICH BEARS:  
 21" FIR N. 50° E. 39.18  
 17" FIR S. 44° W. 3.83  
 N. 45° E. 4.15 TO U.S. F.S. POST

reset: \_\_\_\_\_

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on \_\_\_\_\_

Signed \_\_\_\_\_ P.L.S or R.C.E. No. \_\_\_\_\_

### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_

and examined and filed \_\_\_\_\_

Signed \_\_\_\_\_ P.L.S or R.C.E. No. \_\_\_\_\_

Title \_\_\_\_\_

County Surveyor's Comment COPIED FROM BK 34 PG 5-9