


CORNER RECORD

Document Number _____

City of _____

County of _____, California

Brief Legal Description N 1/4 COR SEC 30 6/22**CORNER TYPE**Government Corner Control Meander Property Rancho Other

Date of Survey _____

COORDINATES (Optional)

N. _____

E. _____


Zone _____ NAD27 NAD83

NAD83 Epoch _____

Elev. _____

Vert. Datum: NGVD29 NAVD88 Meas. Units: Metric Imperial Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:


NORTH 1/4 CORNER SEC. 30 6/22
 FOR 1" I.P. LAIN OVER IN TOE OF FILL FOR "SEY
 RANCH ROAD" AND OLD BLAZE ON 27" CEDAR
 OF UNKNOWN ORIGIN. SET D.S.F.S. MON. IN
 ROCK MD. L.S. 429B, IN TOE OF FILL AT
 W.O. GENTRY CALG. POS. OF 1955 (ORIG. POSITION FROM BT 1/4)
 FROM WHICH BEARS:

A description

11" L. OAK (10F3) S.27°E. 38.40
 16" CEDAR S.6°E. 32.63
 27" CEDAR N.84°W. 12.88 (OLD BLAZE)
 N.45°E. 2.0 TO U.S.F.S. POST

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyor's Act on _____

Signed _____ P.L.S or R.C.E. No. _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed _____

Signed _____ P.L.S or R.C.E. No. _____

Title _____

County Surveyor's Comment COPIED FROM BK 34 PG 5-9