	NER RECORD
	S R. 2/E. M.D.B.4 MERIDIAN CALIF.
	ER () RANCHO () CONTROL () OTHER ()
CORNER IDENTIFICATION DATE OF VISIT	
5º/4 CANER SEC. 34)	
REBUILT ()	GGED () REESTABLISHED OBLITERATED CORNER ()
	INGLE PROPORTION OF THE SO. LINE OF
SEC. 34/7/VI AS THERE WAS A	NO GOOD EVIDENCE OF THE ORIGINAL
BEARING TREES. THE CALLS WE	RE NOT ACCURATE AS TO THE LOCATION
OF THE GANER.	
PHYSICAL DESCRIPTION OF MONUMENTS REBUIL	
SET .P. TAGGED P.C.E	, 5982 FOR S14 Cal.
CALIFORNIA COORDINATE SYSTEM ORDER: FILE STATIONS USED: NOS (USC & GS) () STAT STATION ZONE ELEVATION EASTINGS (X)	
:ASTINGS (X)	
KETCH: (INCLUDE REFERENCE TIE OR WITH	ESS POINTS, REMARKS AND TOPO OF AREA)
NHO ON TAKE	1" 1. P. FOR 5'/4 COR. 34/7/21 1" 1. P. FOR 5'/4 COR. 34/7/21 SPONS 390 SP
	PLANTINE HALL
SURVEYOR'S CERTIFICATE	COUNTY SURVEYOR'S CERTIFICATE
HIS CANALER RECORD WAS PREPARED BY ME	THE CORNER RECORD WAS RECEIVED 8-1-77 and GENERAL
NUNDER MEDIRECTION IN CONFORMANCE	
H THE LAND SURVEYORS ACT ON 6/6	BY: a crote
L. M. JENSEN 6 19 77	TITLE: County Engineer
SIGNED fly for	DOCUMENT NO. 77-13-01
.S. or R.C.E. NO.	STATEMENT ON BACK OF SHEET
NO. 4261 SEAL	YES () NO (>
F OF CALIFORNIA SEAL	
OF CALIFIC	