CORNER RECORD

| | Document Number |
|---|--|
| City of UNINCORPORATED | County of MADERA , California |
| Brief Legal Description LOT 10 OF CORRECTED MAP OF SMAPS AT PAGES 143-144, M.C.R. | SIERRA LAKES TRACT, RECORDED IN BOOK 6 OF |
| CORNER TYPE | COORDINATES(Optional) |
| Government Corner Control Meander Property Rancho Other | N |
| T.7S., R.22E. Date of Survey JULY 21, 2015 | Vert. Datum: NGVD29 NADV88 Meas. Units: Metric Imperial |
| Corner - Left as found Found and tagged | Established Reestablished Rebuilt Rebuilt |
| Identification and type of corner found: Evidence used to identify or p | procedure used to establish or reestablish the corner: |
| REESTABLISHED THE NORTHWEST CORNER OF LOT 10 USING | |
| MONUMENTS OF RECORD. | |
| | |
| | |
| | |
| | |
| A description of the physical condition of the monument as found and | d as set or reset: |
| SET PK NAIL IN ASPHALT WITH ALUMINUM WASHER MARKED | "LS 8779" |
| | |
| | |
| | |
| SURVEYOR'S STATEMENT | LASED LAND SUALIFIC |
| This Corner Record was prepared by me or under my direction | in conformance with |
| the Land Surveyor's Action JULY 21 , 20 | DEWITT No. 8779 |
| | 7/21/15 |
| Signed P.L.S. or R.C.E. No | PLS 8779 |
| COUNTY SURVEYOR'S STATEMENT | |
| This Corner Record was receivedJuly 7, 2015, | and examined and examined DAVID M. McGLASSON |
| and filed August 4, 2015 | DAVID M. |
| Signed David Mily P.L.S. or R.C.E. N | No. PLS 6968 |
| Title Acting County Surveyor | NO. 6900 NO. |
| County Surveyor's Comment | OFCALI |
| | |
| | |
| | |
| | |



CORNER RECORD

LOT 10 OF CORRECTED MAP OF SIERRA LAKES TRACT, RECORDED IN BOOK 6 OF MAPS AT PAGES 143-144, M.C.R. LOCATED IN SECTION 19, T7S, R22E, MDB&M

