


CORNER RECORD

Document Number _____

City of _____

County of Madera, California

Brief Legal Description Parcel 1 of Parcel Map No. 707 Book 19 of Maps Page 63, MCR, Section 19, T. 7 S., R. 22 E., M.D.B & M.



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 2/5/03

COORDINATES(Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elevation _____
 Vert. Datum: NGVD29 NAV88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Reset southeast corner and angle point in east line of Parcel 1.

See page 2 of 2


A description of the physical condition of the monument as found and as set or reset: _____

See page 2 of 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 10 February 2003

Signed [Signature] P.L.S. or R.C.E. Number 5339



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 2/21/03 and examined and filed 2/25/03

Signed [Signature] P.L.S. or R.C.E. Number 6968

Title ACTING CO. SURVEYOR

County Surveyor's Comment Mr. Seaman's Registration is current through 12/31/03.

