


CORNER RECORD

COUNTY OF Madera T. 7 S R. 22 E M.D. MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT MARCH 21 1980



NW cor. Sec 20

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Fd. G.L.O. Brass Cap on 2" O.D. iron pipe up 12" in scattered rock md as per G.L.O. Field Notes by A.W. Brown, U.S. Surveyor dated March 1917


PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Left G.L.O. monument in place. Painted 2" O.D. i.p. red. Set sign post approximately 4' NW of mon with Forest Service 'corner attention sign attached.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

Cor. Ties
*5 35° E 7.02' to shiner & nail (58c N) in jct. Power Pole
 5 20° W 44.36' to 58c N in 11" dia Ponderosa Pine
 N 26° W 22.52' to 58c N in 24" dia Ponderosa Pine*



SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON March 26 1980
 SIGNED: Howard Arnold Cohen
 L.S. or R.C.E. No.: 4689

COUNTY SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____
 BY: Thomas A. Hansen
 TITLE: County Engineer
 DOCUMENT No. _____
 STATEMENT ON BACK OF SHEET