


CORNER RECORD

COUNTY OF MADERA T. 7 S. 23 MDB MERIDIAN CALIFORNIA
 CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



NW COR. SEC. 5

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

5' FT SUGAR DINE

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED


3/4" I.P. WITNESS COR. (LS 4126)
 N 89° 53' 47" E 7.0'

3/4" I.P. WITNESS COR. (LS. 4126) 501° 42' 35" E 7.0'

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NCS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (M) _____ EASTINGS (M) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

18"	INCENSE CEDAR	S 34° E	31.3'
16"	BLACK OAK	S 38° W	24.4'
24"	INCENSE CEDAR	N 8° W	11.4'
15"	" "	N 69° E	11.0'



Rob S MORBY —

(SIKORA LS. 4126)

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____

SIGNED: _____
 I.S. or R.C.E. No.: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____ BY: _____ TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET

YES NO