

CORNER RECORD

COUNTY OF MADERA T. 8 R. 19 MOB: M MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER  MEANDER  RANCHO  CONTROL  OTHER   
CORNER IDENTIFICATION - DATE OF VISIT 10-18 1991



SW 27 8/19

CORNER - LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED OBLITERATED CORNER  REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND, EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

PHYSICAL DESCRIPTION OF

SOUTHWEST CORNER  
OF SECTION 27 8/19  
FOUND 1 3/4" IRON PIPE LEANING 0.5' EAST  
WIRED TO CORNER FENCE POST & 2 ORIG. BT'S  
ALSO FOUND 5/8" REBAR LG. 5509 ALONG SIDE  
AT TRUE POSITION TIES:  
1) CORNER FALLS AT FENCE LINE INTERSECTION S-N-E.  
2) 28" W. OAK WITH BLAZE, S. 74°20'05" E. 22.60 ORIG. BT  
3) STUMP HOLE OF FALLEN 24" W. OAK WITH BLAZE  
N. 39°08'21" E. 92.75 ORIG. BT.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST  SECOND  THIRD   
STATIONS USED: NGS (USC & GS)  STATE  COUNTY  OTHER  STATION \_\_\_\_\_ STATION \_\_\_\_\_  
ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (N) \_\_\_\_\_ EASTINGS (E) \_\_\_\_\_

(Fold)

SKETCH: (Include reference tie or witness points, remarks and topo of area)

COPIED FROM RS 39/147

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON \_\_\_\_\_ 19\_\_\_\_

SIGNED: \_\_\_\_\_

L.S. or R.C.E. No.: \_\_\_\_\_

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED \_\_\_\_\_ 19\_\_\_\_ AND EXAMINED AND FILED \_\_\_\_\_ 19\_\_\_\_

BY: \_\_\_\_\_

TITLE: \_\_\_\_\_

DOCUMENT No. \_\_\_\_\_

STATEMENT ON BACK OF SHEET

YES  NO