


CORNER RECORD

COUNTY OF MADERA T. 8 R. 20 MDB 1/2 MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT 6 19 91



S 1/4 SEC. 4 8/20

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND, EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

SOUTH 1/4 CORNER SECTION 4 8/20, FD. 1" IRON PIPE
CS. 2737, 10'± WEST OF N-S ROAD AS DE R/S 6/192
AS SET FROM ORIG SE BT. DID NOT FIND W/BLD
CORNER AS SET ON SPLIT IN 1924
TIES
1) W. OAK 14" N. 86° E. 40.62 N&T.
2) W. OAK 12" N. 18° E. 80.65 N&T.
3) W. OAK 16" S. 54° E. 69.96 ORK. BT

ALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

(Fold)

SKETCH: (Include reference tie or witness points, remarks and topo of area)

COPIED FROM PM 3287 40/146

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____

SIGNED: _____
L.S. or R.C.E. No. _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____
AND EXAMINED AND FILED _____ 19____

BY: _____
TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET

YES NO