


CORNER RECORD

Document Number \_\_\_\_\_

City of \_\_\_\_\_

County of Madera, California

Brier Legal Description North 1/4 corner of section 7, Township 8 South, Range 21 East, M.D.B.&M



CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey August 29, 1997

COORDINATES (OPTIONAL)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone Datum  
 Elevation \_\_\_\_\_

CORNER -- Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

*Found and accepted monument per Parcel Map 179 filed in Book 15, Page 1, Madera County Records.*


A description of the physical condition of the monument as found and as set or reset:

*Found 1.25" iron pipe up 6" with tag LS 2229.*

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on September 11, 1997.

Signed Tim Davis PLS 7061



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 12 SEP 97 1997 and examined and filed 30 SEP 97 1997.

Signed W.L.R. Miller Title AG. Co. Surveyor



County Surveyor's Comment: \_\_\_\_\_

COUNTY ROAD 415

Nail & tin,  
NE side  
fence post

wire fence

wire fence

20.83'

1.15'

N1/4 section 7

24.64'

Nail & tin,  
NW side  
tree

chain link fence

1" iron pipe,  
up 3", LS 2737

1.25" od fence post,  
second east from  
fence corner

chain link fence



SCALE 1"=10'

082114060