


CORNER RECORD

Document Number _____

City of _____

County of Madera, California

Brief Legal Description _____



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (OPTIONAL)

N. _____
 E. _____
 Zone _____ Datum _____
 Elevation _____

CORNER -- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

Found West Quarter Corner of Section 9, Township 8 South, Range 21 East, Mount Diablo Base and Meridian, per Record of Survey filed in Book 14, Page 28 Madera County Records by C.J. McKee in December, 1966.


A description of the physical condition of the monument as found and as set or reset:

Found 1" iron pipe, up 6", in rock mound, tagged L.S. 2737.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on March 13, 1996

Signed Travis Davis PLS 7061



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 1 APRIL 1996 and examined and filed 9 APRIL 1996.

Signed Mark Rickford Miller Title ACTING COUNTY SURVEYOR



County Surveyor's Comment: _____



SCALE 1" = 10'

○ SET NAIL AND TIN IN WEST SIDE OF 24" BLUE OAK.

○ SET NAIL AND TIN IN NORTHWEST SIDE OF 12" BLUE OAK WITH ORIGINAL BLAZE.

44.79

43.09'

△ WEST QUARTER CORNER SEC 9, T8 S, R21 E, M.D.B. & M.

21.35'

○ SET NAIL AND TIN IN NORTHWEST SIDE OF 24" BLUE OAK.

0821300540