


CORNER RECORD

Document Number _____

City of _____

County of Madera, California

Brie. Legal Description _____



AREA

2/21

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey July 9, 1996

COORDINATES (OPTIONAL)

N. _____
E. _____
Zone _____ Datum _____
Elevation _____

CORNER -- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:
Set at prorated position using original Subdivision corners, Book 40, Pages 32-37, Madera County Records.

A description of the physical condition of the monument as found and as set or reset:
Set #4 rebar, up 6", tagged PLS 7061.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on August 7, 1996.

Signed Travis Davis PLS 7061



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 1996 and examined

and filed 7 FEB 2000 ~~1996~~

Signed MLA ML Title Act. Co. Surveyor

Co. Surveyor's Comment: CORNER RECORD FOUND IN STACK OF OLD PAPER WORK
FILED LATE.

LONGVIEW

LOT 5

(...) Record data per Subdivision Map
filed in book 40, pages 32-37.
Madera County Records.

LANE

LOT 6

LOT 7

Found #5 rebar, up 6', tagged LS 3022

EAST

Set #4 rebar, up 6',
tagged PLS 7061

Found #5 rebar, up 6',
tagged LS 3022

N 77°16'24" E 100.92'
(N 77°15'21" E 101.00')

N 43°21'04" E 170.66'
(N 43°21'26" E 170.74')

LOT 8

LOT 20

0821

LOT 19

