



DESCRIBE CORNER MONUMENT FOUND

Found 2" diameter Iron Pipe with Brass Cap LS 2737 set in a rock mound, not accepted as corner. *Found no evidence of original monument*

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

none

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Madera County Road 274 and USFS Road 7S75 proceed southerly along 7S75 for approximately 5700'. Corner is approximately 250' east of Road in area of pine snags and dead fall.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Agency _____

Signature R. Seaman Title LS 5339 Division _____ Headquarters _____ Date 2/12/95 7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set standard USFS monument on the north line of Section 1 at GLO distance (132') from Gulch to west. CAP MARKED: $\frac{1}{4}$ _____

T7S R22E
 S36
 S1
 T8S R22E
 LS 5339

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

1. A 24" diameter Ponderosa Pine, blazed and scribed "NBT" bears N00°02'E, 18.20'.
2. A 12" diameter Live Oak, the southerly fork, blazed and scribed "NBT" bears S64°21'E, 23.67'.
3. An 11" diameter Cedar, blazed and scribed "NBT" bears S54°28'W, 15.82'.
4. A 2" diameter iron pipe w/Brass Cap LS 2737 bears S00°10'30"E, 3.12'.
5. Set metal post, N45°W 4'

Work Done By R. Seaman Title L.S. Date 2/8/95 State Registration No. 5339 or Agency _____
 Certified Cor. Record Prepared? Yes No Filed At _____ Date _____

REMARKS

Bearings are to the center of the trees, distances are horizontal to a nail and tag LS 5339 driven into the side center of the root crown. Posted USFS monument and bearing tree signs as required.