



DESCRIBE CORNER MONUMENT FOUND
 not applicable

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 not applicable

PHOTO IDENTIFICATION DATA
 Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
 From the intersection of Madera County Roads 222 and 221; northerly along Road 222 approx. 1000' to the posted E-W centerline Sec. 2; thence easterly, along the posted line, approx. 700' to the corner.

PLANE COORDINATE POSITION DATA
 State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Agency _____

Signature R. Seaman Title LS 5339 Division _____ Headquarters _____ Date 5/17/95 7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT
 Set a standard USFS aluminum monument 2 1/2" O.D. X 30" long with a 3 1/2" diameter cap. CAP MARKED: 1/16
 LS 5339 1995

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE
 1. A 12" diameter Black Oak blazed and scribed "NBT", bears N04°27'E, 45.53'.
 2. A 12" diameter Black Oak blazed and scribed "NBT", bears N32°34'E, 61.65'.
 3. A 10" diameter Black Oak blazed and scribed "NBT", bears S04°23'W, 58.41'.
 4. A 1" diameter iron pipe w/no tag bears S82°02'58"W, 4.56'.
 5. Set a post w/54-6 and 54-9 signs S45°E, 4'.

Work Done By R. Seaman Title L.S. Date 5/17/95 State Registration No. 5339 or Agency _____
 Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS
 Bearings are to the center of the trees, distances are horizontal to a nail and tag LS 5339 driven into the side center of the root crown. Posted USFS monument and bearing tree signs as required.