



DESCRIBE CORNER MONUMENT FOUND

Found 2" diameter Iron Pipe with pipe cap marked appropriately for corner. Accepted as set by acceptable methods.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

N/A

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Madera County Roads 221 and 222, southerly along Road 221 for approximately 1600' to the PG&E flume, thence westerly for approximately 950' to the corner.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Agency _____

Signature: *Richard A. Seaman* Title: L.S. 5339 Division: _____ Headquarters: _____ Date: 4/19/95 FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Found 2" diameter Iron Pipe with pipe cap marked:

T8S R22E
 W/1/2 S/2
 S/11
 LS 1969

- ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE
1. A 24" diameter Digger Pine, blazed and scribed "NBT" bears S54°54'W, 32.82'.
 2. A 48" diameter Digger Pine, blazed and scribed "NBT" bears N73°05'W, 53.52'.
 3. A 30" diameter Black Oak, blazed and scribed "NBT" bears N40°20'E, 67.52'.
 4. Set a metal post with USFS signs N45°W, 4'.

Work Done By: R. Seaman Title: L.S. Date: 4/14/95 State Registration No. 5339
 Certified Cor. Record Prepared? Yes No Filed At: _____ Date: _____

REMARKS

Bearings are to the center of the trees, distances are horizontal to a nail and tag LS 5339 driven into the side center of the root crown. Posted USFS monument and bearing tree signs as required.