CORNER RECORD

	County of MADERA , California
City of UNINCORPORATED	
Brief Legal Description PARCEL 4 OF PARCEL MAP RECO	
CORNER TYPE	COORDINATES(Optional)
Government Corner Control Meander Proper Rancho Other T.8S., R.22E. Date of Survey MAY 14, 2015	FZ NADOZ AMADOZ
Corner - Left as found Found and tagged	Established Reestablished Rebuilt
Identification and type of corner found: Evidence used to identify o	r procedure used to establish or reestablish the corner:
FOUND ORIGINAL MONUMENTS OF RECORD, AND USED PRORATION TO REESTABLISH THE MISSING CORNER AT THE	
NORTHWEST CORNER OF PARCEL #4, AS SHOWN ON SHEET	
A description of the physical condition of the monument as found and as set or reset:	
SET 5/8" REBAR, WITH PLASTIC CAP MARKED "LS 8779", UP 6".	
SURVEYOR'S STATEMENT SURVEYOR'S STATEMENT RYAND RYAND	
This Corner Record was prepared by me or under my direction in conformance with	
bio Edita dal Vojei di I	2015
Signed P.L.S. or R.C.E.	No.: PLS 8779
COUNTY SURVEYOR'S STATEME	ENT
This Corner Record was received June 1, 2015,	and examined DAVID M. McGLASSON
and filed, June 23, 2015	DAVID M. CALASSON
Signed David Millson P.L.S. or R.C.E	DI S 6068 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
Title Acting County Surveyor	No.: PLS 0900
	- Action
	2



LEGEND

CORNER RECORD

SURVEY MONUMENT (AS NOTED)

PARCEL 4 OF PARCEL MAP RECORDED IN BOOK—
18 OF MAPS AT PAGE 74, M.C.R.
LOCATED IN SECTION 14, 8/22

O SET 5/8" REBAR, TAGGED LS 8779

PROPERTY LINE

ADJOINING PROPERTY LINE

¾" IRON PIPE NO TAG

SET %" REBAR LS 8779 PARCEL #2 PM 18/74

- (N00°42'43"W 522.51')(M)

(N89°33'24"E 400.00')(M)

¾" IRON PIPE NO TAG

(N00.42'43"W 330.00')(M)

PARCEL #4 PM 18/74



¾" IRON PIPE NO TAG

PARCEL #2 PM 12/26 ¾" IRON PIPE _ LS 4126

JONES SNYDER & ASSOCIATES P.O. BOX 2292, OAKHURST, CA 93644 (559)683-7661 WWW.JSSURVEYING.COM

DATE: MAY 20, 2015 JOB NO: 15-139 DWG FILE: 15-139CR DRAWN BY: RJD