

CORNER RECORD

COUNTY OF MAVERA T. B5 R. 22E M17 MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

IDENTIFICATION — DATE OF VISIT APRIL 16 19 75



S 1/4 COR. SEC 23, T89, R22E, M17

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH


FOUND A 1" IRON PIPE WITH NO IDENTIFICATION, PIPE MAY HAVE BEEN USED AS S 1/4 COR, BUT NO EVIDENCE OR VERIFICATION OF SUCH USE. THEREFORE, SAID PIPE NOT ACCEPTED AS S 1/4 COR.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

SET 3/4" IRON PIPE WITH 1" BRASS CAP. LOCATION DETERMINED BY SINGLE PROPORTION

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 E _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)




SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS' ACT ON May 16 19 75

SIGNED: [Signature]

L.S. or R.C.E. No.: _____



COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED 6-6 19 75 AND EXAMINED AND FILED June 9 19 75

BY: [Signature]
 TITLE: County Engineer

DOCUMENT No. 75-21-05

STATEMENT ON BACK OF SHEET

YES NO